

Claggett Creek Watershed Council - Project Report FORM

Project Coordinator Name: Mark Caillier
 Project Area/site : West Bank of Claggett Creek at Ben Miller Park, Keizer, OR
 Date of project: Saturday, February 20, 2010

Number of volunteers: 16

Hours of volunteer time: 75 (51 planting, 17 planning/acquisition/management, 7 loading/transporting/delivery)

Donations and In-Kind Donations:

Donation	Value	Source	Other Information
(186) Trees & Shrubs	\$ 930	City of Keizer, Marion Soil & Water Conservation District	
(200) Marking/Support Stakes	\$ 75	City of Keizer	
(300) Cardboard Weed Mats	\$ 300	Garten Foundation, City of Keizer	
(25) Trunk Protectors	\$ 50	City of Keizer	
(20) Cubic Yards Compost	\$ 500	Noah Jones, Highway Fuel	Delivered & Blown On
(6) Shovels	\$ 30	Jeff Anderson, City of Keizer, Mark Caillier	
Misc. Supplies	\$ 10	City of Keizer	Alert tape, flags, clip boards, forms, etc.
Use of vehicles to transport equipment and supplies	\$ 80	City of Keizer, Mark Caillier	
Refreshments	\$ 20	City of Keizer	Water, soft drinks, coffee, muggings, croissants
Site Planning/Layout/Orientation/Project Supervision	\$ 600	Elizabeth Sagmiller, Dorothy Deil, Keizer Public Works, Mark Caillier	
TOTAL	\$ 2,595		

PROJECT NARRATIVE DESCRIPTION

Partnerships:

Highway Fuel, Garten Foundation, City of Keizer, Marion Soil & Water Conservation District, Keizer Rotary Pioneers

Goals:

Plant native trees and shrubs along the west bank of Claggett Creek in a prepared site of former Reed Canary grass and Blackberries. Install weed mats and cover with 3-4 inches of compost.

Lessons Learned:

1. Be flexible enough to engage volunteers as they arrive throughout the project to provide a project orientation and instructions. Picking it up as they go along is generally not sufficient or efficient.
2. Portable watering platform will not pull water vertically over four feet.
3. Planting is just the beginning of the 18 month commitment of initial care for the trees and shrubs. Commitment confirmed and supported at March 2010 CCWC meeting.
4. One supervisor/assistant/supporter/inspector/safety officer for every 7-8 workers is necessary and appropriate.